SBD - CM Review Form

To:

Project Review & Analysis - Construction

From:

SBD CM - Eddy V. Etienne Jr.

Environmental Monitoring and Restoration Division -

Department: Department of Regulatory and Economic Resources (RER)

Contact: Karina Martinez

Date:

12/30/2015

Resubmittal: No.

PROJECT NUMBER:

E09-DERM-01-024-CEI

Building 410 at Opa-locka Airport - Source Removal, Reporting, and Monitoring Well

PROJECT TITLE:

Installation on behalf of the Miami-Dade Aviation Department (MDAD)

PROJECT LOCATION:

14201 NW 42nd Ave, Opa-locka, FL 33054

SCOPE OF WORK/DESCRIPTION: The subject project consists of removing and disposing of approximately 290 tons of contaminated soils, site restoration, and reporting.

SPECIAL REQUIREMENTS: Based on site history, contamination exists and therefore any excavation or removal work must be performed by personnel, including subcontractors, which are certified in accordance with OSHA standards in Hazardous Waste Operations and Emergency Response (HAZWOPER); a requirement that the prime contractor meet.

TRADES/SUBTRADES	AMOUNT	PERCENTAGE	COMMENTS
			Hazardous Materials Remediation Contractor
Eng/Planning/MGMT/Oversight/Reporting	\$13,648.66	27.78%	*Special Requirement needed
Equipment & Materials	\$14,843.50	30.22%	
Labor	\$4,798.40	9.77%	
Disposal and Survey	\$15,834.10	32.23%	
BASE ESTIMATE TOTAL	\$49,124.66	100.00%	

Small Business Development Signature:

*Trades/Sub-Trades identified for possible subcontracting opportunities by SBD CM

RER is recommending

0.00%

Date: 12-31-15

1 of 1